


**Attention: ACCU-CHEK® Softclix Lancet User**

Roche Diagnostics announced on May 18, 2009, an issue with a small number of ACCU-CHEK® Softclix lancets that have missing caps (see picture below). Missing caps can lead to an accidental needle stick. The ACCU-CHEK® Softclix lancets that may be affected by this issue were packaged in 10 count packs distributed as samples or as 10 and 17 count packs in the following meter kits:

Meter Kits	REF Number	Lancet Count	Lancet Lot Numbers Affected
ACCU-CHEK® Active Meter Kit	03184501001	10	M25C2, M25C5, M25C7, M32B5, N32A5
ACCU-CHEK® Voicemate Meter	12030802001		
ACCU-CHEK® Aviva Meter kits that include an ACCU-CHEK® Softclix lancing device	04893247001		
CoaguChek XS System for Patient Self-Testing	04837738001		
ACCU-CHEK® Compact Plus Meter Kit	03149137001, 05177294001,	17	M25C9, M25D2, M27D6 M32A8, M32B3

Below are examples of an ACCU-CHEK® Softclix lancet with a missing cap and the location of the lot number on the ACCU-CHEK® Softclix lancets plastic bag:



If you have 10 or 17 count ACCU-CHEK® Softclix lancets, check the lot number on the plastic bag (see chart above), Roche Diagnostics will replace any ACCU-CHEK® Softclix lancets with missing caps. Call ACCU-CHEK® Softclix Lancet Hotline at 1-800-778-7057.